
Laser Training (Class 3 B, 4)

All Laser users (including Principal Investigators) must participate in the University's Laser Safety training course prior to handling or working with class 3B and 4 Lasers. Please ensure that all 3B and 4 Lasers or devices with Class 3B and 4 Lasers are registered with the Radiation Safety Office (EHS).

*Laser users must participate in refresher training **at least every 3 years**.*

Principal Investigators are responsible for ensuring that all Laser users under their supervision:

- are trained in the specific procedures and/or hazards associated with their work;
- participate in the University Laser Training and refresher training at the frequencies indicated above; and
- are compliant with best practices and follow the ANSI Standard when operating with high powered LASERS (Class 3 B and 4)
- have their baseline eyes conducted in accordance with the Occupational Health & Wellness Department
- have LASER Safety Glasses with the proper OD Rating.

All LASER users (including Principal Investigators) must participate in the University's LASER Safety training course prior to handling or working with class 3B and 4 Lasers

*Class 3B and 4 Lasers users must participate in refresher training **at least every 3 years. Passing the quiz with a mark of 75% or greater will suffice as having completed the refresher course.***

Laser Safety user training is provided by the Environment Health & Safety Department at the University of Guelph.

Source

URL: <https://www.uoguelph.ca/hr/about-hr/environmental-health-safety-ehs/ehs-training/course-descriptions/laser-training-class-3-b-4>